



### CARBON SHEET TOLERANCES AND GAGE CHART

GAGE	DECIMAL	Tolerance Range		Lbs./Sq.Ft.
		HR & P&O	CR	
7	0.1793	0.1713 to 0.1873	0.1713 to 0.1873	7.5
8	0.1644	0.1564 to 0.1724	0.1564 to 0.1724	6.875
9	0.1495	0.1415 to 0.1575	0.1415 to 0.1575	6.25
10	0.1345	0.1265 to 0.1425	0.1285 to 0.1405	5.625
11	0.1196	0.1116 to 0.1276	0.1136 to 0.1256	5
12	0.1046	0.0966 to 0.1126	0.0986 to 0.1106	4.375
13	0.0897	0.0827 to 0.0967	0.0847 to 0.0947	3.75
14	0.0747	0.0677 to 0.0817	0.0697 to 0.0797	3.125
15	0.0673	0.0613 to 0.0733	0.0623 to 0.0723	2.813
16	0.0598	0.0538 to 0.0658	0.0548 to 0.0648	2.5
17	0.0538	0.0478 to 0.0589	0.0498 to 0.0578	2.25
18	0.0478	0.0428 to 0.0528	0.0438 to 0.0518	2
19	0.0418		0.0378 to 0.0458	1.75
20	0.0359		0.0329 to 0.0389	1.5
21	0.0329		0.0299 to 0.0359	1.375
22	0.0299		0.0269 to 0.0329	1.25
23	0.0269		0.0239 to 0.0299	1.125
24	0.0239		0.0209 to 0.0269	1